Figure 1

**Figure 2**

Figure 3

**Figure 4**

505 → (**Start**)

500

510 → **Determine Path Width Error**

515 → **Determine Path Drift Error**

520 → **Determine Measurement Resolution Error**

525 → **Combine Errors to Calculate Pilot Phase Measurement RMSE**

530 → (**End**)

Figure 5